

Coaxlink

Coaxlink 11.2.1



PCI 
EXPRESSTM

 **PC/104**
Embedded PC Modules

CoaxPress

Terms of Use

EURESYS s.a. shall retain all property rights, title and interest of the documentation of the hardware and the software, and of the trademarks of EURESYS s.a.

All the names of companies and products mentioned in the documentation may be the trademarks of their respective owners.

The licensing, use, leasing, loaning, translation, reproduction, copying or modification of the hardware or the software, brands or documentation of EURESYS s.a. contained in this book, is not allowed without prior notice.

EURESYS s.a. may modify the product specification or change the information given in this documentation at any time, at its discretion, and without prior notice.

EURESYS s.a. shall not be liable for any loss of or damage to revenues, profits, goodwill, data, information systems or other special, incidental, indirect, consequential or punitive damages of any kind arising in connection with the use of the hardware or the software of EURESYS s.a. or resulting of omissions or errors in this documentation.

This documentation is provided with Coaxlink 11.2.1 (doc build 2088).
© 2019 EURESYS s.a.

Contents

1. Release Benefits	5
2. Release Specification	6
2.1. Products & Accessories	7
2.2. Firmware Variants per Product	8
2.3. CoaXPress Standard Compliance	13
2.4. Supported Operating Systems	14
2.5. Memento	15
2.6. Development Tools	16
2.7. Software Tools	16
3. Important Notices	17
3.1. Firmware Version Requirements	18
3.2. CPU Requirements	19
3.3. Driver Installation on macOS	20
3.4. Driver Installation on Windows	21
3.5. Driver Installation on Windows 7	23
3.6. Driver Installation on Windows Server 2016	24
3.7. Flash EEPROM Change Note	25
4. Release Details	27
4.1. Firmware Variants Support Changes	28
4.2. Added/Improved Features	29
4.3. Solved Issues	30
4.4. Breaking Changes	31
5. Known Issues	38
5.1. Unexpected Issues	39
5.2. Deviations from the CoaXPress specification	40
Host Connections Maps	40
5.3. Deviations from the GenTL specification	47
5.4. Deviations from the PCIe 3.0 specification	49
5.5. Functional Limitations	50

aarch64 ARM Processor Architecture50

1. Release Benefits

Coaxlink 11.2

3-camera firmware variant

This release of Coaxlink supports the "3-camera" firmware variant for **1633 Coaxlink Quad G3** and **1633-LH Coaxlink Quad G3 LH**.

This allows connecting one 2-connection and two 1-connection area-scan cameras to a single Coaxlink card.

Flat field correction for line-scan cameras

This release of Coaxlink adds a flat field correction - FFC - hardware pixel processing stage to the 1-camera line-scan firmware variants of **1633 Coaxlink Quad G3**, **1633-LH Coaxlink Quad G3 LH** and **1635 Coaxlink Quad G3 DF**.

This allows to compensate the differences of light sensitivity between the pixel sensors of a line-scan camera, the differences of illumination intensities in the field-of-view and the differences in the transmission of light through the lens.

2. Release Specification











2.1. Products & Accessories	7
2.2. Firmware Variants per Product	8
2.3. CoaXPress Standard Compliance	13
2.4. Supported Operating Systems	14
2.5. Memento	15
2.6. Development Tools	16
2.7. Software Tools	16

2.1. Products & Accessories

Coaxlink main products

Product	S/N Prefix	Icon
1630 Coaxlink Mono	KMO	
1631 Coaxlink Duo	KDU	
1632 Coaxlink Quad	KQU	
1633 Coaxlink Quad G3	KQG	
1633-LH Coaxlink Quad G3 LH	KQH	
1629 Coaxlink Duo PCIe/104-EMB	KDI	
1634 Coaxlink Duo PCIe/104-MIL	KDR	
1635 Coaxlink Quad G3 DF	KDF	
1637 Coaxlink Quad 3D-LLE	KQE	
3602 Coaxlink Octo	KOC	
3603 Coaxlink Quad CXP-12	KQP	
3620 Coaxlink Quad CXP-12 JPEG	KQJ	

Related accessory products

Product	S/N Prefix	Icon
1625 DB25F I/O Adapter Cable	DBC	
1636 InterPC C2C-Link Adapter	KCC	
3300 HD26F I/O module for Coaxlink Duo PCIe/104	KDM	
3301 Thermal drain (Model 1) for Coaxlink Duo PCIe/104		
3302 DIN1.0/2.3 Coaxial cable for Coaxlink Duo PCIe/104		
3303 C2C-Link Ribbon Cable		
3304 HD26F I/O Adapter Cable		
3610 HD26F I/O Extension Module TTL-RS422	EMA	
3612 HD26F I/O Extension Module TTL-CMOS5V-RS422	EMC	
3614 HD26F I/O Extension Module - Standard I/O Set	EMD	

**NOTE**

- The S/N prefix is a 3-letter string at the beginning of the card serial number.
- Icons are used in this document for tagging titles of card-specific content.

2.2. Firmware Variants per Product

1630 Coaxlink Mono

Firmware Variant	Description	Host Connections Map	Advanced Processing
1-camera	One 1-connection area-scan camera	1D1	LUT

1631 Coaxlink Duo

Firmware Variant	Description	Host Connections Map	Advanced Processing
1-camera	One 1- or 2-connection area-scan camera	1D2	LUT
1-camera, line-scan	One 1- or 2-connection line-scan camera	1D2	LUT
2-camera	One or two 1-connection area-scan cameras	2D11	LUT
2-camera, line-scan	One or two 1-connection line-scan cameras	2D11	LUT

1632 Coaxlink Quad

Firmware Variant	Description	Host Connections Map	Advanced Processing
1-camera	One 1- or 2- or 4-connection area-scan camera	1D4	LUT
1-camera, line-scan	One 1- or 2- or 4-connection line-scan camera	1D4	LUT
2-camera	One or two 1- or 2-connection area-scan cameras	2D22	LUT

1633 Coaxlink Quad G3

Firmware Variant	Description	Host Connections Map	Advanced Processing
1-camera	One 1- or 2- or 4-connection area-scan camera	1D4	FFC LUT CFA
1-camera, 4-data-stream	One 1- or 2- or 4-connection area-scan camera, up to 4 data streams	1D4S4	-
1-camera, line-scan	One 1- or 2- or 4-connection line-scan camera	1D4	FFC LUT
1-slm-camera	Master 4-connection sub-link of an 8-connection 8-connection area-scan camera	1D8SLM4	LUT
1-sls-camera	Slave 4-connection sub-link of an 8-connection 8-connection area-scan camera	1D8SLS4	LUT
2-camera	One or two 1- or 2-connection area-scan cameras	2D22	LUT
2-camera, line-scan	One or two 1- or 2-connection line-scan cameras	2D22	LUT
3-camera	One 1- or 2-connection and one or two 1-connection area-scan cameras	3D211	LUT
4-camera	One or two or three or four 1-connection area-scan cameras	4D1111	LUT
4-camera, line-scan	One or two or three or four 1-connection line-scan cameras	4D1111	LUT

1633-LH Coaxlink Quad G3 LH

Firmware Variant	Description	Host Connections Map	Advanced Processing
1-camera	One 1- or 2- or 4-connection area-scan camera	1D4	FFC LUT CFA
1-camera, 4-data-stream	One 1- or 2- or 4-connection area-scan camera, up to 4 data streams	1D4S4	-
1-camera, line-scan	One 1- or 2- or 4-connection line-scan camera	1D4	FFC LUT
1-slm-camera	Master 4-connection sub-link of an 8-connection 8-connection area-scan camera	1D8SLM4	LUT
1-sls-camera	Slave 4-connection sub-link of an 8-connection 8-connection area-scan camera	1D8SLS4	LUT
2-camera	One or two 1- or 2-connection area-scan cameras	2D22	LUT
2-camera, line-scan	One or two 1- or 2-connection line-scan cameras	2D22	LUT
3-camera	One 1- or 2-connection and one or two 1-connection area-scan cameras	3D211	LUT
4-camera	One or two or three or four 1-connection area-scan cameras	4D1111	LUT
4-camera, line-scan	One or two or three or four 1-connection line-scan cameras	4D1111	LUT

1629 Coaxlink Duo PCIe/104-EMB

Firmware Variant	Description	Host Connections Map	Advanced Processing
1-camera	One 1- or 2-connection area-scan camera	1D2	LUT
1-camera, line-scan	One 1- or 2-connection line-scan camera	1D2	LUT
2-camera	One or two 1-connection area-scan cameras	2D11	LUT

1634 Coaxlink Duo PCIe/IO4-MIL

Firmware Variant	Description	Host Connections Map	Advanced Processing
1-camera	One 1- or 2-connection area-scan camera	1D2	LUT
1-camera, line-scan	One 1- or 2-connection line-scan camera	1D2	LUT
2-camera	One or two 1-connection area-scan cameras	2D11	LUT

1635 Coaxlink Quad G3 DF

Firmware Variant	Description	Host Connections Map	Advanced Processing
1-camera	One 1- or 2- or 4-connection area-scan camera	1D4	LUT CFA
1-df-camera	One 1- or 2- or 4-connection area-scan data-forwarded camera	1DF4	LUT CFA
1-camera, line-scan	One 1- or 2- or 4-connection line-scan camera	1D4	FFC LUT
1-df-camera, line-scan	One 1- or 2- or 4-connection line-scan data-forwarded camera	1DF4	FFC LUT

1637 Coaxlink Quad 3D-LLE

Firmware Variant	Description	Host Connections Map	Advanced Processing
1-camera	One 1- or 2- or 4-connection area-scan camera	1D4	LLE

3602 Coaxlink Octo

Firmware Variant	Description	Host Connections Map	Advanced Processing
1-camera	One 1- or 2- or 4- or 8-connection area-scan camera	1D8	LUT CFA
1-camera, line-scan	One 1- or 2- or 4- or 8-connection line-scan camera	1D8	LUT
2-camera	One or two 1- or 2- or 4-connection area-scan cameras	2D44	FFC LUT CFA
2-camera, line-scan	One or two 1- or 2- or 4-connection line-scan cameras	2D44	LUT
4-camera	One or two or three or four 1- or 2-connection area-scan cameras	4D2222	LUT
4-camera, line-scan	One or two or three or four 1- or 2-connection line-scan cameras	4D2222	LUT
5-camera	One 1- or 2- or 4-connection and one or two or three or four 1-connection area-scan cameras	5D41111	LUT
8-camera	Up to eight 1-connection area-scan cameras	8D11111111	LUT

3603 Coaxlink Quad CXP-12

Firmware Variant	Description	Host Connections Map	Advanced Processing
1-camera	One 1- or 2- or 4-connection area-scan camera	1D4	LUT CFA
1-camera, line-scan	One 1- or 2- or 4-connection line-scan camera	1D4	LUT
4-camera	One or two or three or four 1-connection area-scan cameras	4D1111	LUT

3620 Coaxlink Quad CXP-12 JPEG

Firmware Variant	Description	Host Connections Map	Advanced Processing
4-camera	One or two or three or four 1-connection area-scan cameras	4D1111	CFA JPEG

2.3. CoaXPress Standard Compliance

Coaxlink products together with Coaxlink driver version 5.0 or higher complies with the following versions of the CoaXPress standard:

- CoaXPress Standard 1.0
- CoaXPress Standard 1.1
- CoaXPress Standard 1.1.1
- CoaXPress Standard 2.0 (Preliminary)

The following deviations to the CoaXPress standards apply:

- **For all versions:** Restrictions to the camera connection schemes.

See also: "Host Connections Maps" on page 40.

2.4. Supported Operating Systems

Windows

The Coaxlink driver is designed to support all Windows versions from **7 SP1** to 10, including the server versions, on x86 (32-bit) and x86_64 (64-bit) platforms.

This release has been validated with the following Windows versions:

OS Name & Version	Platform	Notes
Microsoft Windows 7	x86 (32-bit)	Service Pack 1 with the latest updates
Microsoft Windows 8.1	x86 (32-bit)	-
	x86-64 (64-bit)	
Microsoft Windows 10	x86-64 (64-bit)	Version 1809, a.k.a. October 2018 Update



NOTE

- The Coaxlink driver for Windows 10 is signed by Microsoft.
- Power saving modes of the operating systems (StandBy, Sleep, Suspend...) are not supported.

Linux

The Coaxlink driver is designed to be distribution-independent on x86, x86_64, and aarch64 platforms. It is expected to work with a wide range of distributions.

This release has been validated with the following distribution(s):

OS Name & Version	Platform	Notes
Linux CentOS 7	x86 (32-bit)	Kernel version 3.10
Linux Ubuntu 14.04	x86 (32-bit)	Kernel version 3.13
Linux Ubuntu 14.04	x86-64 (64-bit)	Kernel version 3.13
Linux Ubuntu 16.04.1 LTS	aarch64 (64-bit)	Kernel version 4.4.0-57
Linux Ubuntu 17.04	x86_64 (64-bit)	Kernel version 4.10
Linux Ubuntu 18.04.1 LTS	x86_64 (64-bit)	Kernel version 4.18.7



NOTE Power saving modes of the operating systems (StandBy, Sleep, Suspend...) are not supported.

macOS

The Coaxlink driver is designed to support all macOS versions from version 10.12 on x86_64 (64-bit) platforms.

This release has been validated with the following version(s):

OS Name & Version	Platform	Notes
macOS 10.12.6	x86-64 (64-bit)	A.k.a. Sierra
macOS 10.13.4	x86-64 (64-bit)	A.k.a. High Sierra



NOTE

- The Coaxlink driver for macOS is signed by Euresys using a certificate that has been signed by Apple.
- Power saving modes of the operating systems (StandBy, Sleep, Suspend...) are not supported.

2.5. Memento

Memento version 4.0 or later is required when using Coaxlink driver version 4.0 or later.

Memento version 9.5 is required to use the Memento Analyzer.

2.6. Development Tools

The Coaxlink driver is supplied as GenICam GenTL producer libraries (coaxlink.cti):


- An x86 dynamic library designed to be used with ISO-compliant C/C++ compilers for the development of x86 applications.
- An x86_64 dynamic library designed to be used with ISO-compliant C/C++ compilers for the development of x86_64 applications.
- An aarch64 dynamic library designed to be used with ISO-compliant C/C++ compilers for the development of aarch64 applications.
- A .NET assembly designed to be used with development environments compatible with .NET frameworks version 2.0 or higher.

The Coaxlink cards should be usable with any development tool that supports at least one of these interfaces.

2.7. Software Tools

Tool Name	Tool Description
Coaxlink Firmware Manager	Tool for installing or upgrading the firmware embedded on the Coaxlink cards.
GenICam Browser (64-bit)	64-bit version of the GUI tool giving access to all the GenICam features exposed by the GenTL Producer(s) in your system
GenICam Browser	32-bit version of the GenICam browser
GenTL Console (64-bit)	64-bit version of the command-line tool giving access to all the functions and commands exposed by the Euresys GenTL Producer
GenTL Console	32-bit version of the GenTL Console

3. Important Notices

 **WARNING** Important notifications to be read before installing and/or using the product on your PC!

- 3.1. Firmware Version Requirements18
- 3.2. CPU Requirements19
- 3.3. Driver Installation on macOS20
- 3.4. Driver Installation on Windows21
- 3.5. Driver Installation on Windows 723
- 3.6. Driver Installation on Windows Server 201624
- 3.7. Flash EEPROM Change Note25

3.1. Firmware Version Requirements

! **WARNING** Important notification to be read before installing and/or using the product on your PC!


Coaxlink 11.2

The following table lists the minimum firmware version numbers(s) required to use Coaxlink driver 11.2.:

Product/Firmware Variant Combinations	Min. Firmware Version Number
All firmware variants of 3602 Coaxlink Octo , 3603 Coaxlink Quad CXP-12 and 3620 Coaxlink Quad CXP-12 JPEG	290
All firmware variants of other products	294

! **WARNING** If the requirement is not satisfied for all the Coaxlink cards in your system, it is **mandatory** to apply the Firmware Upgrade procedure prior to using this version of the driver.

NOTE
 The Coaxlink driver checks the compatibility of the firmware installed on every Coaxlink card. For Coaxlink cards having an incompatible firmware, the GenTL driver exposes 0 (zero) Device and the GenICam browser displays a "Firmware too old" error message:



"Firmware too old" error message

3.2. CPU Requirements



WARNING Important notification to be read before installing and/or using the product on your PC!

The image converter requires a CPU that has the Supplemental Streaming SIMD Extension 3 (SSSE3) instruction set.

3.3. Driver Installation on macOS



WARNING Important notifications to be read before installing the driver on your macOS PC!

Memento and Coaxlink Installers

This notice applies when installing Coaxlink or Memento Euresys drivers on macOS

After Memento and Coaxlink package files have been downloaded with **Safari**, the usual *double-click* to launch the installer will not let you install the package.

You shall use instead *control+click* and select *Open* to launch the installer. A window will pop up, click then on *Open* to proceed.

macOS High Sierra or later

This notice applies when installing Coaxlink or Memento Euresys drivers on macOS High Sierra or later

Starting with macOS High Sierra, the user has to manually approve loading of third-party kernel extensions.

See also: https://developer.apple.com/library/content/technotes/tn2459/_index.html

The first time Memento and Coaxlink drivers are installed, their kernel extensions have to be approved.

A window about blocked extensions might pop up during the package installation.

Go to *Preferences* → *Security & Privacy* and ensure that **System software from developer "Euresys SA" was blocked from loading.** is not displayed. If so, click on *Allow*.


3.4. Driver Installation on Windows



WARNING Important notification to be read before installing the driver on your Windows PC!

The following Windows Security warning messages may occur at driver installation on Microsoft Windows:


Always trust Euresys code-signing certificate



This Windows security warning occurs when the Euresys code-signing certificate is missing from the "Trusted Publishers" Windows Certificate store. This happens, for instance, when the Euresys code-signing certificate must be renewed.

Follow the instructions to install the current Euresys code-signing certificate into the "Trusted Publishers" Windows certificate store.

Missing time-stamping certificate



This Windows security warning occurs when the VeriSign Universal Root CA certificate for time-stamping is missing from the Windows certificate store.

This issue can be solved by installing this missing certificate, which is available in an archive that can be downloaded [here](#), on the Symantec website.

3.5. Driver Installation on Windows 7



WARNING Important notification to be read before installing Euresys drivers on your Windows 7 PC!

Renewal of the "Code Signing For Microsoft Authenticode" certificate for Euresys drivers and SHA-256 support

Microsoft Windows 7 and Microsoft Windows Server 2008 R2 now require at least SP1 as well as some specific Windows updates in order to support SHA-256 certificates.

The following Windows update is required and must be installed before using Euresys drivers on Microsoft Windows 7 and Microsoft Windows Server 2008 R2:

- [KB3033929](#) (provides support for SHA-256 certificates which are required by Microsoft): without this one, a "Windows cannot verify the digital signature for the drivers required for this device" (code 52) error will prevent the Euresys drivers from loading.

3.6. Driver Installation on Windows Server 2016




WARNING Important notification to be read before installing Euresys drivers on your Windows Server 2016 PC!

This notice applies to :

- Coaxlink driver since version 4.7

When installing Euresys drivers on a fresh install of Windows Server 2016, the UEFI Secure Boot feature must be disabled in BIOS so that the Euresys drivers can be loaded by Windows when Secure Boot is enabled.



Device Manager error message

3.7. Flash EEPROM Change Note



WARNING Important notification to be read before installing and/or using the product on your PC!

Several Coaxlink products will undergo a hardware change of the Flash EEPROM control logic.



NOTE The Flash EEPROM is the memory that stores the contents of the Coaxlink's on-board FPGA.

Affected products list

Product	S/N Prefix	First Serial Number of New Cards
1629 Coaxlink Duo PCIe/104-EMB	KDI	10,000
1633 Coaxlink Quad G3	KQG	10,000
1633-LH Coaxlink Quad G3 LH	KQH	10,000
1634 Coaxlink Duo PCIe/104-MIL	KDR	10,000
1635 Coaxlink Quad G3 DF	KDF	10,000
1637 Coaxlink Quad 3D-LLE	KQE	10,000

Consequences

Existing applications using a Coaxlink driver prior to version 10.0.0 are required to use a new procedure to install or update the firmware on new boards.

The change has no impact for applications already using Coaxlink driver 10.0.0 or higher.

With the exception of the firmware update, the change has strictly no impact on the product functionality, performance and specifications:

- The hardware design of these new cards, including the CoaXPress interface, PCI Express interface, the FPGA and the I/O, has not been changed.
- The functionality, performance and specification of the new cards is guaranteed to remain unchanged. Once programmed with the corresponding firmware, the new cards remain compatible with all previous versions of the Coaxlink driver.



TIP For further information, read the *D207EN-Flash EEPROM Change Note PDF* document on the PDF Guides page.



NOTE Coaxlink related PDF documents are available online at the following URL: https://documentation.euresys.com/Products/Coaxlink/Coaxlink/en-us/Content/00_Home/PDF_Guides.htm.

4. Release Details

4.1. Firmware Variants Support Changes	28
4.2. Added/Improved Features	29
4.3. Solved Issues	30
4.4. Breaking Changes	31

4.1. Firmware Variants Support Changes

Coaxlink 11.2

Added firmware variant

Target Product	Firmware Name	Description
1633 Coaxlink Quad G3	3-camera	One 1- or 2-connection and one or two 1-connection area-scan cameras <ul style="list-style-type: none"> • Host Connections Map: 3D211 • Advanced processing: LUT

Improved firmware variants

Target Product	Firmware Name	Description
1633 Coaxlink Quad G3	1-camera, line-scan	Added FFC advanced processing
1635 Coaxlink Quad G3 DF	1-camera, line-scan	Added FFC advanced processing
1635 Coaxlink Quad G3 DF	1-df-camera, line-scan	Added FFC advanced processing

4.2. Added/Improved Features

Coaxlink 11.2

Sample programs

`ffc-wizard`: added line-scan mode to the sample application and improved documentation with screenshots.

4.3. Solved Issues

Coaxlink 11.2

Undetected Coaxlink cards after firmware upgrade

[QuadG3](#)[QuadG3LH](#)[Duo104EMB](#)[Duo104MIL](#)[QuadG3DF](#)[Quad3DLLE](#)

11.2.1: Fixed firmware issue that prevents detection of **1633 Coaxlink Quad G3, 1633-LH Coaxlink Quad G3 LH, 1635 Coaxlink Quad G3 DF, 1637 Coaxlink Quad 3D-LLE, 1629 Coaxlink Duo PCIe/104-EMB** and **1634 Coaxlink Duo PCIe/104-MIL** Coaxlink cards on some PC after an upgrade to firmware versions 288 or 290.

CoaXPress discovery

Fixed unreliable discovery when several master connections (i.e. several cameras) were connected to the same Coaxlink Device.

GenICam data stream XML

Fixed data stream XML to reflect that packed pixel formats (**UnpackingMode=Off**) functionality is not available on line-scan firmware variants.

Visual Studio Compiler

Removed Visual Studio Compiler warnings (*warning C4100: unreferenced formal parameter*) from `EGenTL` and `EGrabber` header files.

NVIDIA Jetson

Added a workaround for the NVIDIA Jetson Xavier and TX2 running on L4T R31.1 and L4T R32.1 (`pci_alloc_consistent` ignoring `pci_set_consistent_dma_mask` issue).

macOS

Fixed a regression introduced in 10.6.0 that could potentially lead to undefined symbols being used in Coaxlink binaries on macOS Sierra 10.12.

4.4. Breaking Changes



WARNING Changes in the API that are not backward compatible.

Since Coaxlink 11.1

Quad3DLLE

Behavior of 1637 Coaxlink Quad 3D-LLE from firmware revision 285.

The line pitch alignment has been changed to 16 bytes (before firmware revision 285, the line pitch alignment of the card was 8 bytes); this means the `Width` of the camera must be a multiple of 16 (`MONO8`).

When the extraction is disabled, the card behaves like an area-scan variant (and the data stream feature **BufferHeight** is not available); when the extraction is enabled, **BufferHeight** is available and determines the number of profiles to extract; when the extraction is disabled, applications no longer require extra care to make sure acquisitions always start with the first line of the acquired images.

CoaXPress

Ignore any remote device whose master connection is not connected to the first connector of a Coaxlink Device; the driver now requires a master connection to be connected to the first connector whereas the extension connections can be connected to the remaining Coaxlink Device connectors in any order.

See also: ["Firmware Variants per Product" on page 8](#) and ["Host Connections Maps" on page 40](#) for the applicable connection schemes.

Updated `ImageConvertInput` and `ImageConvertOutput` structures

Subsequent potential build issues can be fixed by either:

- using `IMAGE_CONVERT_INPUT` and `IMAGE_CONVERT_OUTPUT` initialization macros (recommended approach) or
- adding the suffix `Version0` to `ImageConvertInput` and `ImageConvertOutput` types



NOTE Users of EGrabber are not affected by this breaking change

Since Coaxlink 10.3

PayLoadSize Behavior

The feature `PayLoadSize` is not available anymore when the remote device `Width` is not in line with the data stream `Width.Inc`

Since Coaxlink 10.2

Additional constructor parameter required

The grabber classes (based on `EGrabber`) instantiated by `EGrabbers` require the additional constructor parameter (`bool remoteRequired`).

See also: sample "[213-egrabbers](#)" for details

Since Coaxlink 10

Deprecated functions from namespace `Euresys`

Deprecated the functions `Features`, `RegexFeatures`, `GlobFeatures`, `EnumEntries`, `RegexEnumEntries`, `GlobEnumEntries` from namespace `Euresys`, which are still available by `#defining EURESYS_USE_NS_EURESYS_DEPRECATED_API`.



TIP Two options to fix user code:

- *Recommended change* Replace all occurrences of:
 - `Euresys::Features()` by `Euresys::query::features()`
 - `Euresys::RegexFeatures(re)` by `Euresys::query::features().regex(re)`
 - `Euresys::GlobFeatures(g)` by `Euresys::query::features().glob(g)`
 - `Euresys::EnumEntries(f)` by `Euresys::query::enumEntries(f)`
 - `Euresys::RegexEnumEntries(f, re)` by `Euresys::query::enumEntries(f).regex(re)`
 - `Euresys::GlobEnumEntries(f, g)` by `Euresys::query::enumEntries(f).glob(g)`
- Or add `#define EURESYS_USE_NS_EURESYS_DEPRECATED_API` before `#include <EGrabber.h>` (or `#include <EGenTL.h>`), a quick fix that doesn't require changing source code.

Since Coaxlink 9.3.1

Removed data stream event counts from the list of possible contexts of device event notifications

Removed data stream event counts from the list of possible contexts of device event notifications.

StartOfCameraReadoutEventCount, **EndOfCameraReadoutEventCount**, **StartOfScanEventCount**, **EndOfScanEventCount**, **RejectedFrameEventCount**, and **RejectedScanEventCount** are no longer valid values for **EventNotificationContext1**, **EventNotificationContext2**, and **EventNotificationContext3** in the device module.

Since Coaxlink 9.3

Reset of StartOfScanTriggerSource, EndOfScanTriggerSource and ScanLength features

Data stream features **StartOfScanTriggerSource**, **EndOfScanTriggerSource** and **ScanLength** are now reset by the data stream feature **StreamReset**. Previously, they were reset by the device feature **DeviceReset**.

Since Coaxlink 9.2

GenAPI Features Range Checking

Range checking will prevent applications from setting forbidden values to camera features. A meaningful error will be reported if such an event should happen.

Since Coaxlink 9.1.1

Camera Model - Exposure Time Range Boundaries

When **ExposureTimeMin** and/or **ExposureTimeMax** are/is set, the order in which the features **ExposureTimeMin**, **ExposureTimeMax** and **ExposureTime** are set is imposed by the constraints.

Since Coaxlink 7.1.1

GenTL 1.5 Header File

Moved to standard GenTL 1.5 header file (was previously GenTL 1.4):

- GenTL 1.5 changed namespace from `GenICam::Client` to `GenTL`,
- Coaxlink custom GenTL definitions have been moved accordingly from the namespace `GenICam::Client::Euresys` to namespace `GenTL::EuresysCustomGenTL`,
- replaced header file `GenTL_v1_4.h` by `GenTL_v1_5.h`,
- replaced header file `GenTL_v1_4_EuresysCustom.h` by `GenTL_v1_5_EuresysCustom.h`.

Euresys::GenTL Class Renaming

Renamed the class `Euresys::GenTL` into `Euresys::EGenTL` to avoid name conflicts with the new standard GenTL 1.5 namespace `GenTL`. This will impact any code using the class `Euresys::GenTL`:

- renamed header file `EuresysGenTL.h` into `EGenTL.h`,
- renamed header file `EuresysGenTLErrors.h` into `EGenTLErrors.h`,
- `Euresys::EGenTL` is now declared in header file `EGenTL.h`.

Deprecated Euresys::SharedGenTL Class

Deprecated the class `Euresys::SharedGenTL`, which is still available by defining `EURESYS_USE_SHAREDGENTL_DEPRECATED_API`.



TIP

Two options to fix user code:

- *Recommended change* Replace all occurrences of `Euresys::SharedGenTL` by `Euresys::EGenTL`,
- Or add `#define EURESYS_USE_SHAREDGENTL_DEPRECATED_API` before `#include <EGrabber.h>`, a quick fix that doesn't require changing source code.

GenTL 1.5 Changes

Announcing or revoking buffers while acquiring returns the error code `GC_ERR_BUSY` (was `GC_ERR_RESOURCE_IN_USE` for GenTL 1.4)

Revoking a queued buffer returns the error code `GC_ERR_BUSY` (was `GC_ERR_RESOURCE_IN_USE` for GenTL 1.4)

New device access status values (defined by GenTL 1.5) returned by the GenTL functions `IFGetDeviceInfo` and `DevGetInfo` for the command `DEVICE_INFO_ACCESS_STATUS`:

GenTL 1.5 Changes

- `DEVICE_ACCESS_STATUS_OPEN_READWRITE`: when the device is opened by the current producer with read/write access
- `DEVICE_ACCESS_STATUS_OPEN_READONLY`: when the device is opened by the current producer with read-only access

Since Coaxlink 7.0.0

OemSafetyKey Length

The length of **ProgramOemSafetyKey** and **CheckOemSafetyKey** is now limited by a user-configurable **MaximumOemKeyLength** (4096 characters by default)

LUT Configuration Locking

LUT configuration features (datastream) are locked while grabbing.

CIC Features Availability

Features related to the CIC (device) are not available when **CameraControlMethod** is **NC** or **EXTERNAL**.

Since Coaxlink 4.6.1

EGrabber API

Deprecated EGrabber method `announceBuffer` (superseded by `announceAndQueue`).

Two options to fix user code:



TIP Recommended change Replace all occurrences of `announceBuffer` by `announceAndQueue (GenTLMemory (...))` or `announceAndQueue (UserMemory (...))`,



TIP Or add `#define EURESYS_USE_EGRABBER_DEPRECATED_API` before `#include <EGrabber.h>`.

Since Coaxlink 4.5.1

Euresys Name Space for EGrabber Classes

EGrabber C++ classes now belong to `Euresys` namespace.

Two options to fix user code:



TIP *Recommended change* Replace each occurrence of `EGrabber` by `Euresys::EGrabber`,



TIP Or add `using namespace Euresys;` after `#include <EGrabber.h>`.

Since Coaxlink 4.4.1

EGrabber API

The API of `EGrabber` .NET classes have changed since Coaxlink 4.4.0 beta

`GenTL` class now behaves like `SharedGenTL`, which is what most users need

- The `GenTL` constructor accepts a new argument, named `shared`, which can be used to revert to the old behavior.

RGBConverter.h

Added `inplace1x2yeReordering` methods instead of `Inplace1x2yeReordering` class

- User code needs to be adapted to call `inplace1x2yeReordering` instead of creating an `Inplace1x2yeReordering` instance, please see `include/RGBConverter.h` for a code sample.

Since Coaxlink 4.4.0

.NET Assembly

Added new assembly exposing `EGrabber` classes, previous `CoaxlinkGrabber` classes are removed from the assembly.

EGrabber

Deprecated `getInfoString` methods (replaced by `getInfo`).

Two options to fix user code:



TIP Recommended change Replace all occurrences of `getInfoString<module>` (and `getBufferInfoString`) by `getInfo<module, std::string>` (and `getBufferInfo<std::string>`)



TIP Or add `#define EURESYS_USE_EGRABBER_DEPRECATED_API` before `#include <EGrabber.h>`.

GenTL C++ class

Deprecated `bayerConvert`

Though the function `bayerConvert` is superseded by the image converter, it is still possible to use it, if required please add `#define EURESYS_USE_BAYER_DEPRECATED_API` before `#include <EuresysGenTL.h>` or `#include <EGrabber.h>`

Since Coaxlink 4.3

Data Stream Module GenICam Feature

`UnpackingMode`: Changed default value to LSB (instead of MSB)

Since Coaxlink 4.1

Device Module Features

Merged **CycleTriggerSource** and **CycleHardwareTriggerSource** features.

Renamed **CycleSoftwareTrigger** into **StartCycle**.

Renamed **CyclePeriodTarget** into **CycleMinimumPeriod**.

Renamed **ErrorCounter** into **ErrorCount**.

Renamed **ErrorCounterReset** into **ErrorCountReset**.

Removed backward compatibility for deprecated features: `TriggerSource`, `TargetFramePeriod`, `ExposureRecovery`.

5. Known Issues

- 5.1. Unexpected Issues 39
- 5.2. Deviations from the CoaXPress specification 40
 - Host Connections Maps 40
- 5.3. Deviations from the GenTL specification 47
- 5.4. Deviations from the PCIe 3.0 specification 49
- 5.5. Functional Limitations 50
 - aarch64 ARM Processor Architecture 50

5.1. Unexpected Issues

Coaxlink 11.1

Inoperative unpacking mode for line-scan firmware variants

Affected Product

All Coaxlink products (having a line-scan firmware variant).

Affected Driver Versions

All Coaxlink releases.

Issue Description

The line-scan firmware variants don't support **UnpackingMode = Off**.

Workaround

There are no workaround.

5.2. Deviations from the CoaXPress specification

Host Connections Maps40

Host Connections Maps

The CoaXPress standard suggests that Devices (cameras or data forwarding devices) can be connected to the Host (frame grabber) using a free connection scheme. Instead, the Host Interface of Coaxlink requires a specific assignment of the Device connections to the Host connectors. Such assignment is named **Host Connections Map**.

The Host Connections Map is hard-coded in the product firmware variant.



WARNING The Coaxlink product and firmware variant must be selected according to the required mapping!

Host Connections Map naming convention

The **Host Connections Map** or **HCMAP** designates how the connections of the Host Interface of a Coaxlink card are allocated to the Devices (cameras).

A Host Connection Map - HCMAP - is designated by an acronym using the following Euresys proprietary naming convention:

```
<dev#><dev-type> [<str#>S] {<con#>...<con#>} [<SL-con#>]
```

where:

- <dev#> declares the maximum number of Devices (cameras) that can be attached to the Host Interface.
 - 1 for a single-device Host interface
 - 2 for a 2-device Host interface
 - ...
- <dev-type> declares the device type.
 - D for standard CoaXPress devices
 - DF for virtual devices used in the Data Forwarding schemes
- <con#> declares the number of connections available for each device. *This field is repeated once for each device.*
 - 1 for a single-connection device

- 2 for 2-connection device
 - ...
- <str#>S declares the maximum number of data streams allowed by a device.
 - This field is omitted when there is only 1 stream
 - 4S for a up to 4 data-streams per device
- SL<-con#> declares the number connections per sub-link.
 - *This field is omitted when there are no sub-links.*
 - SL4 for a 4-connection sub-links

Examples

HCMAP **2D22** designates a Host Interface with 2 standard 1-data-stream CoaXPress Devices and 2 connections for each device.

HCMAP **1D4S4** designates a Host Interface with 1 standard CoaXPress Devices, up to 4 data streams, and 4 connections per device.


1D1 host connections map

One 1-connection device




1D2 host connections map

One 1- or 2-connection device




1D4 host connections map

One 1- or 2- or 4-connection device




1D8 host connections map

One 1- or 2- or 4- or 8-connection device




1D4S4 host connections map

One 1- or 2- or 4-connection device, up to 4 data streams



1D8SLM4 host connections map


Master 4-connection sub-link of an 8-connection device



See also: [8-connection CoaXPRESS Cameras](#) for the connection scheme of an 8-connection camera to two Coaxlink cards.

1D8SLS4 host connections map


Slave 4-connection sub-link of an 8-connection device



See also: 8-connection CoaXPress Cameras for the connection scheme of an 8-connection camera to two Coaxlink cards.

1DF4 host connections map


One 1- or 2- or 4-connection device



See also: CoaXPress Data Forwarding for the connection schemes of slave Data Forwarding devices.


2D11 host connections map

One or two 1-connection devices




2D22 host connections map

One or two 1- or 2-connection devices




2D44 host connections map

One or two 1- or 2- or 4-connection devices




3D211 host connections map

One 1- or 2-connection and one or two 1-connection devices




4D1111 host connections map

One or two or three or four 1-connection devices




4D2222 host connections map

One or two or three or four 1- or 2-connection devices




5D41111 host connections map

One 1- or 2- or 4-connection and one or two or three or four 1-connection devices



8D11111111 host connections map

Up to eight 1-connection devices



5.3. Deviations from the GenTL specification

EventKill

The GenTL specification states that:

- In case of multiple pending wait operations `EventKill` causes one wait operation to return with a `GC_ERR_ABORT` error code.
- This means that if more than one thread waits for an event, the `EventKill` function terminates only one wait operation and other threads will continue execution.
- Therefore in order to cancel all pending wait operations `EventKill` must be called as many times as wait operations are pending.
- In case this function is called while no wait operation was pending the next call to `EventGetData` will return a `GC_ERR_ABORT`.

This specification is nothing but the behavior description of a particular implementation based on a Windows auto-reset event.

This implementation is prone to race conditions: calling `EventKill` N times in a row to kill exactly N waiting threads is not guaranteed to work as expected because signaling an event that is already in the signaled state has no effect. In other words, some of the `EventKill` calls could have no effect.

`EventKill` as specified is not easy to use: How many `EventKill` calls are required? How many `EventGetData` calls should we expect to return `GC_ERR_ABORT`? Note that race conditions affect these questions.

The Euresys GenTL implementation solves these issues, but differs slightly:

- `EventKill` aborts all pending wait operations on the event handle.
- `EventKill` has no impact on subsequent wait operations.

DSStopAcquisition

The GenTL specification states that:

- Each call to `DSStartAcquisition` must be accompanied by a call to `DSStopAcquisition`.
- Argument `iNumToAcquire` passed to `DSStartAcquisition` sets the number of filled/delivered buffers after which the acquisition engine stops automatically.
- There must be a call to `DSStopAcquisition` accompanying each call to `DSStartAcquisition` even though the stream already stopped because the number of frames to acquire was reached.
- `DSStopAcquisition` returns `GC_ERR_RESOURCE_IN_USE` when the acquisition engine has already been terminated or has not been started.

The reasons for this behavior is not clear.

The Euresys GenTL implementation differs slightly:

- `DSStopAcquisition` will not return `GC_ERR_RESOURCE_IN_USE` if the data stream hasn't been started.
- `DSStopAcquisition` will not return `GC_ERR_RESOURCE_IN_USE` if the data stream has already been stopped by a prior call to `DSStopAcquisition`.
- `DSStopAcquisition` will not return `GC_ERR_RESOURCE_IN_USE` if the data stream has stopped automatically after `iNumToAcquire` images have been captured.

In other words, `DSStopAcquisition` is idempotent.

With the Euresys implementation, it is not necessary to treat some errors as normal, and race conditions (between `DSStopAcquisition` and the automatic stop of the data stream) are avoided. Furthermore, if the data stream has stopped automatically after acquiring `iNumToAcquire` images, `DSStartAcquisition` can be called without first calling `DSStopAcquisition`.

5.4. Deviations from the PCIe 3.0 specification

Applies to: [QuadG3](#) [QuadG3LH](#) [QuadG3DF](#)

1633 Coaxlink Quad G3, 1633-LH Coaxlink Quad G3 LH and **1635 Coaxlink Quad G3 DF** operate only at PCIe 2.0 and PCIe 3.0 link speeds.

These products cannot be used when inserted in PCIe revision 1.x slots.

5.5. Functional Limitations

aarch64 ARM Processor Architecture50

aarch64 ARM Processor Architecture

Image converters

The image conversion functions for the aarch64 ARM processor architecture don't use the ARM NEON general-purpose SIMD engine.